Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE2168/1
Work Order Type: Weatherization
Audit Name: Audit (243)

CLIENT INFORMATION

Client Name: Boswell, Percy Address:
Client ID: 50005DE2168

Alt. Client ID:

CLIENT CONTACT INFORMATION

Boswell, Percy (901) 233-0036 Applicant/Person of Record

<u>AGENCY INFORMATION</u>

Agency: Delta Human Resource Agency

Agency Phone: (901) 476-5226

Address: P. O. Box 634 **Fax:** (901) 476-5258

Covington, TN 38019 *Email Address:* Gloria.V.Williams@tn.gov

Agency Contact: Martin, Darrell L. Work Phone:

Cell Phone: (901) 262-8090

Email Address: DarrelllMartin@bellsouth.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Measures

Measure 1 Insta	all 18,000Btu Heat/Coo	l Unit		Componer Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Cooling Equipment		Each	1					
2 Labor	Labor		1					
Other Detail						1 ———		
			Measur	e Sub Total:			Sub Total:	
Measure 2 Insta attic	ıll Electrical blank cov	er plates i	n	Component Estimated				Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
1 Windows	Material	Each	1		7 0 1 1 1			
2 Labor	Labor		1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

		all Foundation Vent 16"	x8"		Componen	ts		ı	Inspected
C	Comment				Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	Labor		1					
2	Construction Materials/Hardwar e	Material	Each	1					
(Other Detail						1		
Ļ									
				Moasur	e Sub Total:]]	Sub Total:	
г				Measur	e Sub Total.				
	Measure 4 Repl	ace 28"x12" Broken Pa	ane in WD	#3	Componen Estimated			l Actual	Inspected
C	_		ane in WD		-		Qty		Inspected
C	Comment	ace 28"x12" Broken Pa Description / Comment Material		#3 — Qty 1	Estimated	1	Qty	Actual	
C #	Comment Material / Labor	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
C # 1	Comment Material / Labor Windows	Description / Comment Material	Units	Qty 1	Estimated	1	Qty	Actual	
C # 1	Material / Labor Windows Labor	Description / Comment Material	Units	Qty 1	Estimated	1	Qty	Actual	
C # 1	Material / Labor Windows Labor	Description / Comment Material	Units Each	Qty 1 1	Estimated	1		Actual	

Report Run On: 5/24/2010

	Measure 5 Rep	lace 28"x24" Broken P	ane in WD	#1	Componen	ts		ı	Inspected
Ī					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Material	Each	1					
2	Labor	Labor		1					
C	Other Detail				,		1		
				Moasu	re Sub Total:			Sub Total:	
Г	Field Notes:			Measur	e oub rotal.				
		lace Side Door Only to htherstripping/Threshol			Componen	ts			Inspected
4	Motorial / Labor	December / Comment	Unito		Estimated	Total	<u> </u>	Actual	Total
	Material / Labor Doors	Description / Comment Material	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
	Labor	Labor		1					
	Other Detail	Labor		•					
	Julei Detail								
				Mossu	e Sub Total:]	Sub Total:	
				Measui	e Sub Total.		· ·	Sub Total.	

Report Run On: 5/24/2010

	Measure 7 Infi	Itration Redctn			Componer	nts			Inspected
C	Block 8 Block 8 Door S	& Seal Air Conditioner WE & Seal Air Conditioner WE & Seal Air Conditioner WE weep Front Door erstrip Front Door)#2		Estimate	d			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
10		Infiltration Reduction	Each	1		rotar	Qiy		Total
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 8 DW comment	H Tank Insulation			Componer	nts			Inspected
					Estimated	 -		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Report Run On: 5/24/2010

Measure 9 DW	/H Pipe Insulation			Componen	ts		ı	nspected
Comment				Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 10 Flo	oor Ins. R-19			Componen				Inspected
				Estimated			Actual	
# Material / Labor1 Insulation	Ploor Insulation - Fiberglass Batts - R-19	<i>Units</i> SqFt	Qty 1075	Unit Cost	Total	Qty	Unit Cost	Total
Other Detail] [] [
			Measur	e Sub Total:			Sub Total:	
Field Notes:						-		

ription / Comment rier Needed t/Crawlspace)	Units Each		Estimated Unit Cost Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
rier Needed	Each	1 Measure	Unit Cost	Total		Unit Cost	
rier Needed	Each	1 Measure	e Sub Total:			Sub Total:	
		Measure	L	ts			Inspecte
			L	ts			Inspecte
			L	ts			Inspecte
			L	ts			Inspecte
			Componen	ts			Inspecte
			Componen	ts			Inspecte
			Componen	ts			Inspecte
i/Crawispace)							
			Estimated	1		Actual	
ription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
ment / crawlspace · barrier	Each	1					
•	Hour	1					
		Measure	e Sub Total:] ;	Sub Total:	
			Measur	Measure Sub Total:	Measure Sub Total:	Measure Sub Total:	Measure Sub Total: Sub Total: